

Annexure D

BUILDING SAFETY CERTIFICATE

Dated: 18/02/2025

No. _____

It is certified that the existing building PRATAP PUBLIC SCHOOL (name of the building or premises) at JUNDLA, KARNAL

(address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	1	1	1	2	2	1

The building is owned/occupied by PRATAP PUBLIC SCHOOL, JUNDLA (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of PWD, B & R (Name of Department/ Govt.) on _____ (date of inspection) in the presence of DR. KUSUM AHLAWAT, PRINCIPAL (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from _____ for a period of _____ years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on _____ at _____ by _____

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : _____

Name : SANJEEV TANWAR

Designation : Sub Divisional Engineer

Name & Address of Department/ Office : PSO Assandh

68 | Page

Sanjeev
22.4.25

Sub Divisional Engineer
Provi., Sub Division
P.W.D. B & R, Assandh

PRINCIPAL
PRATAP PUBLIC SCHOOL
JUNDLA

Scanned with OKEN Scanner